

Traffic and Road Concerns

Issues

Holly Road

The road is in poor condition with pot holes constantly reopening.

Holly Road has a blind bend, and a junction just afterwards. Most vehicles have to go on other side of road to pass parked vehicles - Lack of signage.

A childcare centre is located along Holly Road. Children safety is a concern - lack of signage.

A children's play area is located along Holly Road and Valley Road. Children crossing roads - lack of signage

Pathway access lead straight onto the road. Been children running straight into the road.

Valley Road

Speeding by visitors and external delivery drivers

There has been many near misses at the junction in Valley Road and Elder Crescent. The road layout is not clear enough to drivers. Many vehicles do not stop or slow down. There is a give way sign however it's high up the pole and not in direct view.

Residents and staff has witnessed too many near misses.

The road is in poor condition and rain flows down like a river.

Remedial Requests and Suggestions

Holly Road

20's plenty signage - There is a maximum of 20 MPH speed limit all over Wattisham Flying Station

Oncoming vehicles in middle road signage

Children warning signage

School signage

Speed bumps

Improved White line markings

Valley Road

20 plenty signs - To bring it in line with the 20 MPH speed limit all over Wattisham Flying station

Children warning signage

A change to traffic priority on the Valley Road junction

New white lines and bold STOP painted onto the road

Speed humps to slow traffic down

The use of a SID would also be a good idea.

Angela Douglas

Welfare Reception/Admin Officer

Wattisham Information & Support Centre (WISC) 2 Valley Rd, Wattisham Flying station, Ipswich, IP7 7RE.